



Attorney Docket No. 1594.1227

cf/ef

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Jong-Chull SHON et al.

Application No.: 10/632,802

ATTENTION

Confirmation No.: 7463

CERTIFICATE OF CORRECTION

Filed: August 4, 2003

BRANCH

Certificate

U.S. Patent No.: 6,921,889 *B2*

FEB 13 2006

Issued: July 26, 2005

of Correction

For: MAGNETRON, AND MICROWAVE OVEN AND HIGH FREQUENCY HEATING APPARATUS EACH EQUIPPED WITH THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP
01 FEB 18 11
00000086 6921889
100.00 OP

Date: *Feb 8, 2006*

By: *[Signature]*
Gene M. Garner, II
Registration No. 34,172

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

FEB 14 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,921,889 *B2*

DATED : July 26, 2005

INVENTOR(S) : Jong-Chull SHON et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 9, line 33, change "upper" to --inner--.

Column 9, line 65, change "upper" to --inner--.

Column 10, line 11, change "upper" to --inner--.

Column 10, line 16, change "upper" to --inner--.

* Column 10, line 51, change "slanted portion portion" to --slanted portion--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY
1201 New York Avenue, N.W.
7th Floor
Washington, DC 20005

PATENT NO. 6,921,889

No. of add'l copies
@ 304 per page

⇒

FEB 14 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,921,889 *B2*

DATED : July 26, 2005

INVENTOR(S) : Jong-Chull SHON et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 9, line 33, change "upper" to --inner--.

Column 9, line 65, change "upper" to --inner--.

Column 10, line 11, change "upper" to --inner--.

Column 10, line 16, change "upper" to --inner--.

* Column 10, line 51, change "slanted portion portion" to --slanted portion--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY
1201 New York Avenue, N.W.
7th Floor
Washington, DC 20005

PATENT NO. 6,921,889

No. of add'l copies
@ 304 per page

⇒

FEB 14 2006